

CASE STUDY ON RESOLVING OIL WHIRL ISSUES ON GAS COMPRESSOR

John J. Yu, Ph.D.
Nicolas Péton
Sergey Drygin, Ph.D.

GE Oil & Gas

Abstract

- This case is a site vibration issue on a Gas compressor module. When machine was running at partial load condition, vibration at compressor DE and NDE bearings suddenly increased and tripped the machine.
- This case study outlines how the high vibration issue was successfully diagnosed using shaft relative vibration data.
- The high vibration of 346 $\mu\text{m pp}$ (14 mil pp), higher than nominal bearing clearances, was due to subsynchronous 0.37X component forward precession. Significant shaft centerline thermal influence was detected.
- Oil Whirl condition, was diagnosed at compressor bearings.
- Bearing modification was suggested to the OEM. Length/Diameter bearings ratio was decreased by pads machining from both sides. Follow-up tests after bearing modification confirmed no vibration issue afterwards at any load condition.

Machine Information

Machine Overview



Machine Information


Compressor Mechanical Data

Motor Speed	: 1497 rpm
Compressor Speed	: 5877 rpm
Compressor 1st Lateral Critical Speed	: 2786 rpm
Compressor 2 nd Lateral Critical Speed	: 9042 rpm
Rotating Direction View from Drive End	: Clockwise
Shaft Seal Type	: Labyrinth
DE Bearing Clearance	: 0.250-0.293 mm
NDE Bearing Clearance	: 0.190-0.233 mm
Compressor Bearing Type	: Plane Sleeve
Balance Piston Seal Clearance	: 0.85-1.07 mm

Design Operating Condition:


Flow Rate	: 168685 m ³ /h (224144 kg/h)
Suction Pressure	: 0.99 Bar abs.
Suction Temperature	: 35 deg C
Discharge Pressure	: 3.063 Bar abs
Discharge Temperature	: 169 deg C

Design Operating Curve



Problem Description

Machine Trend Diagram



Background

When machine was running at partial load condition, vibration at compressor DE and NDE suddenly increased and tripped machine.

Example condition before the first tripped on 29th Dec 2015


- Discharge pressure : 0.86 Barg
- Air Flow Rate : about 182000 kg/hour
- Discharge Temperature: about 125 deg C
- Suction Temperature : about 33 deg C

Example condition before the first tripped on 15th January 2016
(after realignment)

- Discharge pressure : 1.14 Barg
- Air Flow Rate : about 287000 kg/hour
- Discharge Temperature: about 152 deg C
- Suction Temperature : about 33 deg C


Process condition during trip events

Machine tripped at different operating conditions.




Shaft Speed Trend


KT-5350252	∠°	RPM	26NOV2015 16:03:36	59 rpm	NA
Air Blower		From 24NOV2015 08:00:00 To 25JAN2016 11:52:00	Historical	Alarm + Transient + Trend	
KT-5350350	∠°	RPM	26NOV2015 16:03:27	233 rpm	NA
Air Blower		From 24NOV2015 08:00:00 To 25JAN2016 11:52:00	Historical	Alarm + Transient + Trend	




Compressor Overall Vibration (Abnormal)




VXT-5350350	—	∠45° Right	Direct	25JAN2016 11:52:00	12 um pp	5873 rpm
Air Blower	From 24NOV2015 08:00:00 To 25JAN2016 11:52:00			Historical	Alarm + Transient + Trend	
VYT-5350350	—	∠45° Left	Direct	25JAN2016 11:52:00	14 um pp	5873 rpm
Air Blower	From 24NOV2015 08:00:00 To 25JAN2016 11:52:00			Historical	Alarm + Transient + Trend	
VXT-5350351	—	∠45° Right	Direct	25JAN2016 11:52:00	18 um pp	5871 rpm
Air Blower	From 24NOV2015 08:00:00 To 25JAN2016 11:52:00			Historical	Alarm + Transient + Trend	
VYT-5350351	—	∠45° Left	Direct	25JAN2016 11:52:00	22 um pp	5875 rpm
Air Blower	From 24NOV2015 08:00:00 To 25JAN2016 11:52:00			Historical	Alarm + Transient + Trend	



Gearbox Overall Vibration (Normal)








VYT-5350256	—	∠30° Left	Direct	24NOV2015 08:00:00	1 um pp	0 rpm
Air Blower	From 24NOV2015 08:00:00 To 25JAN2016 11:52:00			Historical	Alarm + Transient + Trend	
VXT-5350256	—	∠60° Right	Direct	24NOV2015 08:00:00	1 um pp	0 rpm
Air Blower	From 24NOV2015 08:00:00 To 25JAN2016 11:52:00			Historical	Alarm + Transient + Trend	
VYT-5350257	—	∠30° Left	Direct	24NOV2015 08:00:00	1 um pp	0 rpm
Air Blower	From 24NOV2015 08:00:00 To 25JAN2016 11:52:00			Historical	Alarm + Transient + Trend	
VXT-5350257	—	∠60° Right	Direct	24NOV2015 08:00:00	1 um pp	0 rpm
Air Blower	From 24NOV2015 08:00:00 To 25JAN2016 11:52:00			Historical	Alarm + Transient + Trend	





Data Analysis

Overview




- Overview from 27 NOV
- Air Blower data from 27 Nov 2015
 - Blower Vibration rpm
 - Blower Vib
 - Blower orbit
 - Blower Brg Temp
 - Blower Shaft Centerline
 - Blower Shaft Axial Position
- Air Blower data 01 DEC 2015 no Trip
- Air Blower data 02 DEC 2015 No Trip
- Air Blower data 05 DEC 2015 1100-1145 (TRIP)
- Air Blower data 05 DEC 2015 1424-1645 (Not Trip)
- Air Blower data 16 DEC 2015 0910 (Trip)
- Air Blower data 16 DEC 2015 1730-1930 (Trip NDE Y)
- Air Blower data 21 DEC 2015
- Air Blower data 28 DEC 2015 2108 (Trip)
- Air Blower data 29 DEC 2015 1707 (first trip)
- Air Blower data 29 DEC 2015 1707 (second trip)
- Air Blower data 29 DEC 2015 1707 (third trip)
 - Blower Vibration rpm
 - Blower Vib
 - Blower orbit
 - Blower Brg Temp
 - Blower Shaft Centerline w rpm stamp
 - Blower Shaft Axial Position
 - Blower Shaft Centerline w Time stamp
 - Blower Shaft Centerline
- Air Blower data 29 DEC 2015 1707 (three cycle)
 - Blower orbit
 - Blower Brg Temp
 - Blower Shaft Centerline w rpm stamp
 - Blower Vibration rpm
 - Blower Vib
 - Blower Shaft Axial Position
 - Blower Shaft Centerline w Time stamp
 - Blower Shaft Centerline
- Air Blower data current value
- Air Blower data 20160115 SU Aft reAlignment transient
- Franze Plot Session 1 Current Value
- Franze Plot Session 1 Historical Value
- all


Shaft Speed vs. Vibration Amplitude Trends: **Vibration suddenly increased**




Vibration Amplitude: Higher than bearing Clearance (>293 um)





Vibration Spectrum: 0.371X Dominant




DE and NDE orbits: In-Phase



Average Shaft Centerline: Significantly Different btw Cold and Hot Condition



(not orbit or polar plot)




AMPLITUDE: 20 um/div



Diagnostics Summary


Vibration Information Summary

Amplitude	: More than Bearing Clearance (293 um)
Dominant Frequency	: 0.37X (2175 cpm) (< 1 st Res Freq.)
nX Vector	: 0.37X, DE and NDE are in-Phase.
Shaft Position	: Near Bearing Center
Orbit Shape	: Slightly Elliptical Shape, Forward Precession



**Fluid Induce Instability – Whirl
(most likely at DE bearing)**

Fluid Whirl/Whip





Immediate Recommendations

1. Inspect Bearing and Seal Components

2. Check piping support, if any restriction.

3. Confirm Alignment / Correction


First Inspection



Piping Support inspection



Alignment Confirmation



Nom		
No 1	<i>pt. install.</i>	-0.40
No 2	<i>Redhead</i>	-0.52
No 3	<i>+0.2 shim</i>	-0.42
No.4	<i>-0.2 + 0.5 shim</i>	-0.05

102 original → new


Direction view: From Gear to Compr

Bearing Inspection




What else to fix the problem?

Excessive Bearing Clearance



NO

Coupling Misalignment



NO

After adjust
alignment, problem
still existed.

Bearing design issue



Needs to consult
with the OEM

Corrective Action

Corrective Action


A. Adjust External Alignment (btw Coupling): This would help if problem is not severe. >> Already tried, but not successful.

B. Change Lube Oil Temperature: not permanent solution. >> system could not further decrease oil temperature.


C. Decrease Lube Oil Flow Rate: Risk to damage other bearings.

D. Bearing Modification: must be designed and approved by machine manufacturer.


Bearing Design to break Circumferential Oil Flow Pattern




Two Axial-Groove




Three-Lobe




Elliptical



Offset Cylindrical



Tilting Pad



Pressure Dam


Solution

Bearing modification (suggested by OEM)



After bearing modification


Speed Trend



After bearing modification (Cont.)


Vibration Amplitude, 25 um pp (1 mil pp)

VXT-5350350	∠45° Right Direct	25JAN2016 03:39:02	11 um pp	5869 rpm
Air Blower	From 23JAN2016 08:08:00 To 25JAN2016 12:00:45	Historical	Alarm + Transient + Trend	
VYT-5350350	∠45° Left Direct	25JAN2016 03:44:02	16 um pp	5867 rpm
Air Blower	From 23JAN2016 08:08:00 To 25JAN2016 12:00:45	Historical	Alarm + Transient + Trend	
VXT-5350351	∠45° Right Direct	25JAN2016 03:44:04	19 um pp	5866 rpm
Air Blower	From 23JAN2016 08:08:00 To 25JAN2016 12:00:45	Historical	Alarm + Transient + Trend	
VYT-5350351	∠45° Left Direct	25JAN2016 03:44:02	25 um pp	5867 rpm
Air Blower	From 23JAN2016 08:08:00 To 25JAN2016 12:00:45	Historical	Alarm + Transient + Trend	




After bearing modification (Cont.)

Frequency, 1X dominant (normal)




After bearing modification (Cont.)

Orbit plots shows normal dynamic shaft movement



After bearing modification (Cont.)



Discussions

- Oil whirl frequency tracks with speed, usually at $< 0.5X$ ($< 50\%$ running speed frequency). If the frequency is exactly $\frac{1}{2} X$, the instability is not oil whirl, instead it is parametric excitation (rub contact or bearing looseness).
- Oil whip frequency locks into one of the natural frequencies of rotor-bearing system, usually the lowest. As speed goes up, the frequency remains unchanged.
- Subsynchronous vibration could also be caused by aerodynamic instability such as stall or surge in compressors.
- Oil whirl/whip is affected by speed, bearing types and design, lube oil temperature and supply pressure, while aerodynamic instability in compressors is affected by flow condition.

The End

Thank You